

Release Notes for BD600+ V2.750

This document covers software version 2.750. It has a number of fixes for problems in the previous versions.

General Update Information

Eventide recommends that its Broadcast Products are only updated when strictly necessary, as there is a small risk to any update, and it takes time to perform. Read and understand the following Release Notes and only update if you really need the described changes or have or may encounter the problems which it fixes.

These updates require a PC with Windows 7, 8 or 10. Versions of Windows below 10 will require a driver to be installed (see Installing “BD600+USB Drivers.pdf” in the zip file below).

To update the unit, you will need a copy of “217030 Software Installation” – this is a ZIP file and would usually be downloaded from the Eventide Web Site.

Un-zip the file (“extract all”) and run “bd600_update.bat”. Follow the instructions on the screen.

You should normally re-initialize after upgrade (Hold down RAMP_TO_ZERO at powerup). Following this, all settings will be set to their default values.

Release Notes for *BD600+* V2.750

This is a modest upgrade and does not need the previous release to be installed prior to the update, unless the SEND command is to be used.

Problems fixed:

- BD600E Serial Delay would not pass data under some circumstances.
- There could be a difference of about 0.005 seconds between the displayed delay value and that obtained by use of the Serial Remote Control ‘T’ command.

Known Issues

- none

Release Notes for *BD600+* V2.700

This is a significant upgrade and has a multi-step installation procedure.

Problems fixed:

- **PASS Password** does not work – if set, even if the password key is used as described in the User Manual, **CONFIG** mode cannot be entered. To remove the password, the unit must be re-initialized.
- **Restore Factory Defaults - PANIC button** does not work – it asks you to “RELEASE KEY” but does not affect settings. **Clear all Memory – RAMP TO ZERO** must be used instead.
- **PULS** only works on BD600E+ and BD600W+, not BD600+.

Release Notes for BD600+ V2.750

- **BYP** mode **MUTE** is the same as **RLA** – no mute.
- If an unsuitable **SYNC** source is selected in **CONFIG** mode, there is no unlock display indication until the unit leaves **CONFIG** mode.
- If **SEND** is used, and a USB cable is connected to the BD600+ and a computer, yet no computer application is using the **SEND** data, the BD600+ front panel operations will significantly slow down until either the USB is disconnected, or a suitable application is started. Audio is unaffected.

Known Issues

- none

Release Notes for BD600+ V2.651

Original production release.